



























1h



A	B	C (mm)			D
1	L99-1014	2000	300	22	2/4
2	L99-1015	2000	300	22	2/4
3	L99-4005	250	100	15	2/4
4	L99-4007	1732	261	18	2/4
5	L99-4009	145	100	15	2/4
6	L99-4030	1450	950	36	1/4
7	L99-4031	1446	304	22	1/4
8	L99-4032	1400	261	18	1/4
9	L99-5005	1450	410	76	4/4
10	L99-9008	1730	536	6	3/4



16x



Ø7x50 mm

16x



Ø6,3x16 mm

6x



Ø8x30 mm

4x



M6x84 mm

8x



M6x20 mm

13x



Ø20x3mm

2x



130x34x34/2 mm

6x



Ø4x30 mm

12x



Ø15x12 mm #16

12x



20/11

4x



Ø10x16 mm

1x
















4 mm

D





2/4

1 §2 §6



2 §6


8x
Ø15x12 mm #16 r1


3 §6



4x
Ø7x50 mm e1

4x
Ø6.3x16 mm e7




4x
M6x84 mm j117

4x
Ø10x16 mm r43




1x
4 mm z1






4 



5 



6 **7**